NMB
LIGHTING

CLSD Programming Instructions

Step 1: Verify you have the following materials:

PC for programming

CLSD004 Programming Cable

CLSD004 Programming Box

CLSD001 Series LED Driver to be programmed

Step 2: Verify you have completed the installation process. If not, please download the onetime NMB Technologies Programming Utility installation at:
http://www.nmbtc.com/lighting/install

**Step 3**: Plug the USB Connector end of the Programming Cable into the PC

Step 4: Plug the Mini-USB connector end of the Programming Cable into the CLSD004 Programming Box.

Step 5: Remove the dust and moisture barrier tape from the CLSD001 Driver. Set this aside for re-application when the driver programming has been completed.

Step 6: Run the NMB Lighting LED Driver Utility from the Start Menu

Step 7: Place and hold the CLSD004 Programming Box on the CLSD001 Driver, making sure the pins line up with the holes in the driver enclosure. Maintain contact.

Step 8: The LED Driver model and parameters will be automatically detected.

**Step 9**: Select and Click the "Connect" button

Step 10: Select the desired output current

and click the Save button.

Step 11: The Status on the screen will change to Save Complete, and you have now programmed the output current to 0.48 A.

Additional driver modules can be programmed with subsequent "Save" clicks.

Step 12: Replace the dust/moisture barrier tape over the programming holes in the CLSD001 Driver.

Programming Complete.

For more information, please visit: http://www.nmbtc.com/lighting

Or e-mails us directly at: lighting@nmbtc.com